

April

STATE OF UTAH  
DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING  
1594 West North Temple - Suite 1210  
Box 145801  
Salt Lake City, Utah 84114-5801  
Telephone: (801) 538-5291  
Fax: (801) 359-3940

RECEIVED

JAN 30 2014

DIV. OF OIL, GAS &amp; MINING

**LARGE MINING OPERATIONS PROGRESS REPORT**  
**January 1, 2013 to December 31, 2013**

The information required in this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, and the rules as under the Utah Minerals Regulatory Program.



1. Mine Permit Number: M / 049 / 005
2. Mine Name: Jim Gay
3. Name of Operator/Permittee: Pabco Clay Products LLC, dba Interstate Brick Company  
 Note: If Operator's address, company representative or phone number have changed, please provide a replacement page to the Notice of Intention together with form MR-REV available on the Division's web page at [https://fs.ogm.utah.gov/pub/mines/minerals\\_related/forms/MR-REV.pdf](https://fs.ogm.utah.gov/pub/mines/minerals_related/forms/MR-REV.pdf)
4. Report the gross amount of ore mined and waste moved:  










Gross Ore Mined	<u>7,359</u>	Tons, or	<u>      </u>	yd <sup>3</sup>
Waste Material Moved	<u>est 14,000</u>		<u>      </u>	
Tons, or		yd <sup>3</sup>		
5. New disturbance created during the year 0 Acres  
 A reclaimed during the year 0 Acres  
 Total disturbed area at the end of the year 59 Acres\*  
 \*The total disturbed area should not be greater than the permitted/bonded acreage
6. Briefly describe the reclamation work performed during the past year. (Submit form MR-SITE ([https://fs.ogm.utah.gov/pub/mines/minerals\\_related/forms/MR\\_SITE.pdf](https://fs.ogm.utah.gov/pub/mines/minerals_related/forms/MR_SITE.pdf)) to apply for full or partial bond/site release). Attach additional sheets if needed.  
Mining was done on a clay seam that had been buried under overburden by prior mining. The overburden moved was deposited to the north and east in the bottoms of older pits from where material has been removed.
7. Include an updated map depicting surface disturbance and reclamation performed during the year (Rule R647-4-105).

**I hereby certify, under penalties of law, the information provided in this report is true and correct to the best of my knowledge and belief.**

Name (Typed or Print): John Hewitt  
 Title of Operator: Asst. Pld. Mgr.  
 Signature of Operator: [Signature]  
 Date: 1-30-14


**Pabco Clay Products, LLC dba Interstate Brick**



-  2013 Mining Location  
 2013 Roads used in Mining  
 2013 Mined Clay Stockpile  
 2012 Mined Clay Stockpile  
 2012 Mining Areas of Overburden Redistribution for Reclamation Count  
 Clay Mined in 2012  
 2010 Est. Disturbed Area - 57 Acres  
 Davis lease area boundary
- 
- Solters Pass Quadrangle Map  
 T1S, R1E, SW4SW4 Sec 7  
 T1S, R1E, NW4NW4 Sec 18  
 T1S, R1W, NE4NE4 Sec 13  
 T1S, R1W SE4SE4 Sec 12



Solite is Pass Quadrangle Map  
 T1S, R1E, SW4SW4 Sec 7  
 T1S, R1E, NW4NW4 Sec 18  
 T1S, R1W, NE4NE4 Sec 13  
 T1S, R1W SE4SE4 Sec 12  
 as of April 2003, J.H.



Copyright: © 2013 National Geographic Society, Inc.